

Building Technology Services,

Inc

13833 Wellington Trace E4-157
Wellington, Florida 33414

Invoice

Date	Invoice #
5/31/2013	92227

Bill To
The Goodman Company Attn: Bob Saffron

Ship To
150 Worth Ave #224 Palm Beach, FL 33480

P.O. No.	Terms	Project
	Net 30	

Quantity	Description	Rate	Amount
2	Service call-5/31/13; Found indoor fan motor intermittently failing due to bearings and unit in need of maintenance. Replaced indoor fan motor, run capacitor, air filter, and performed full maintenance-Unit needed refrigerant (R-22), added same. Charge should be monitored in the future in case a leak exists.	72.00	144.00
1	20x20x1 pleated filter	6.99	6.99
1	5 mfd run capacitor	11.00	11.00
1	FHP 3-speed fan motor	169.00	169.00
1.5	R22 REFRIGERANT LBS	31.00	46.50
	Sales Tax	6.00%	14.01

Thank you for your business.	Total	\$391.50
------------------------------	--------------	-----------------

Phone # 561-712-1126	Fax # 561-712-1407	ccampbell_bts@bellsouth.net
----------------------	--------------------	-----------------------------