

**Building Technology Services,  
Inc**

13833 Wellington Trace E4-157  
Wellington, Florida 33414

# Invoice

Date	Invoice #
6/10/2013	92234

<b>Bill To</b>
Hayat Holdings 2201 Corporate Blvd., #203 Boca Raton, FL.

<b>Ship To</b>
21084 Black Maple Lane Boca Raton, FL. 33428

<b>P.O. No.</b>	<b>Terms</b>	<b>Project</b>

Quantity	Description	Rate	Amount
2	Service call-6/10/13; Water leak. Found (2) split-systems essentially running without filters with evap coils plugged causing upstairs air handler to freeze/thaw causing the water leak. Cleaned evap coils, drains, installed filters, and checked operation on both systems	72.00	144.00
1	Coil cleaner	26.00	26.00
2	Custom size pleated filters (13.5"x17.5")	7.50	15.00
	Sales Tax	6.00%	2.46

Thank you for your business.	<b>Total</b>	<b>\$187.46</b>
------------------------------	--------------	-----------------

Phone # 561-712-1126	Fax # 561-712-1407	ccampbell_bts@bellsouth.net
----------------------	--------------------	-----------------------------