

**Building Technology Services,  
Inc**

13833 Wellington Trace E4-157  
Wellington, Florida 33414

# Invoice

Date	Invoice #
6/19/2013	92235

<b>Bill To</b>
Hayat Holdings 2201 Corporate Blvd., #203 Boca Raton, FL.

<b>Ship To</b>
7162 Via Firenze Boca Raton, FL.33433

P.O. No.	Terms	Project

Quantity	Description	Rate	Amount
1.5	Service call-6/19/13; Check upstairs a/c. Found system low on refrigerant and a high liquid-line temerature due to dirty/aging condenser coil. I was able to clean coil well enough to bring coil performance into an acceptable range. Added 3.5 lbs R-22 to bring charge to full. Evaluated serveral other aspects of system operation before pinpointing an internal plumbing problem in the evapoator coil for which replacement is the only cure. System supply air is 5 degrees colder than when I arrived, but it will never be as cold as it should be unless evap coil is replaced.	72.00	108.00
3.5	LBS R22 REFRIGERANT	28.00	98.00
	Sales Tax	6.00%	5.88

Thank you for your business.	<b>Total</b>	<b>\$211.88</b>
------------------------------	--------------	-----------------

Phone # 561-712-1126	Fax # 561-712-1407	ccampbell_bts@bellsouth.net
----------------------	--------------------	-----------------------------