

**Building Technology Services,
Inc**

13833 Wellington Trace E4-157
Wellington, Florida 33414

Invoice

| | |
|----------|-----------|
| Date | Invoice # |
| 7/8/2013 | 92253 |

| |
|--|
| Bill To |
| The Goodman Company Attr: Bob Saffron |

| |
|----------------|
| Ship To |
| Bay #214 |

| | | |
|-----------------|--------------|----------------|
| P.O. No. | Terms | Project |
| | Net 30 | |

| Quantity | Description | Rate | Amount |
|----------|---|-------|--------|
| 1.5 | Check a/c and perform full maintenance-7/8/13; Found unit had not had a filter installed in a few years and evap coil was packed with dirt. Unit was low on refrigerant (R-22). Performed full coil cleaning, maintenance, added R-22, and tightened a leaking Schraeder valve. Unit running well at this time. | 72.00 | 108.00 |
| 2 | R22 REFRIGERANT LBS | 28.00 | 56.00 |
| | Sales Tax | 6.00% | 3.36 |

| | | |
|------------------------------|--------------|-----------------|
| Thank you for your business. | Total | \$167.36 |
|------------------------------|--------------|-----------------|

| | | | | |
|---------|--------------|-------|--------------|-----------------------------|
| Phone # | 561-712-1126 | Fax # | 561-712-1407 | ccampbell_bts@bellsouth.net |
|---------|--------------|-------|--------------|-----------------------------|