## **Building Technology Services,**

inc

13833 Wellington Trace E4-157 Wellington, Florida 33414

## **Invoice**

Date	Invoice #
10/13/2012	255509

Bill To		
The Goodman Company Attn: Bob Saffron	• .	

P.O. No.	Terms	Project
	Net 30	

Quantity	Description	Rate	Amount
	1 No cool-10/10/2012; Found unit tripped on low pressure due to lack of refrigerant. Added system sealant and added 2 lbs. R-22 to bring charge to	72.00	72.0
	full.	28.00	56.0
	2 R22 REFRIGERANT LBS. 1 E-Z Seal system sealant	81.00	* 81.
	Sales Tax	6.00%	8
	Janes Lux		
		:	
	·		
	1		
			1
			<u> </u>

Thank you for your business.

Total

\$217.22

Phone #

561-712-1126

Fax # 561-712-1407

ccampbell\_bts@bellsouth.net

## **Building Technology Services,**

Inc

13833 Wellington Trace E4-157 Wellington, Florida 33414

## **Invoice**

Date	Invoice #
10/13/2012	255508

Bill To		
The Goodman Company Attn: Bob Saffron		

Ship To	
150 Worth Ave, Bay 236 Palm Beach, FL 33480	

P.O. No.	Terms	Project
	Net 30	

Quantity	Description	ļ	Rate	Amount
	No cool-10/8/2012; Found unit shut down on condensate pump reservation float switch due to failed pump motor. Replaced pump and checker	evoir d	72.00	108.0
_	operation-okay		79.00	79.0
1	Beckett HD condensate pump Sales Tax		6.00%	4.7
		1		
			,	
		- [		
		•		
				!
				:
			,	
		İ		
				ļ
				1
		1		

Thank you for your business.

Total

\$191.74

Phone #

561-712-1126

Fax # 561-712-1407

ccampbell\_bts@bellsouth.net