

**Building Technology Services,
Inc**

13833 Wellington Trace E4-157
Wellington, Florida 33414

Invoice

Date	Invoice #
12/16/2012	258975

Bill To
2201 Corporate Realty Associates, LLC 2201 NW Corporate Blvd., #205 Boca Raton, FL. 33431

Ship To
2201 NW Corporate Blvd. Boca Raton, FL. 33431

P.O. No.	Terms	Project
	Net 30	

Quantity	Description	Rate	Amount
1	Service call-12/3/12; Reset tripped VFD starter overload then reset unit controller. Operation-ok	72.00	72.00
1	Service call-12/11/12; Found circuit#2 down due to failed outdoor fan motor, all 3 fuses blown and fan blade hub rusted and fused to motor shaft.	72.00	72.00
1	Replaced fan motor, blade, and fuses as quoted (motor-\$620, blade-\$195, fuses-\$60)	875.00	875.00
1	Service call-12/13/12; Found unit controller tripped with "Rooftop Module Data Storage Error" alarm. Reset controller and checked unit operation-ok	72.00	72.00
	Sales Tax	6.00%	0.00

Thank you for your business.

Total \$1,091.00