

Building Technology Services,

13833 Wellington Trace E4-157 Wellington, Florida 33414

Invoice

Date	Invoice #	
10/7/2013	92345	

T3 * 11	PER .
FG111	10

2201 Corporate Realty Associates, LLC 2201 NW Corporate Blvd., #203 Boca Raton, FL. 33431

Ship	To

2201 NW Corporate Blvd. Boca Raton, FL. 33431

P.O. No.	Terms	Project
	Net 30	

1 1 1	Service call-10/7/13; Air compressor motor won't run. Found motor had windings shorted to open. Quoted repair completed 10/8/13; Replace air compressor motor. A-48 fan belt	72.00 550.00	72.0
1	Quoted repair completed 10/8/13; Replace air compressor motor.	550.00	
1	Quoted repair completed 10/8/13; Replace air compressor motor. A-48 fan belt	550.00	
1	A-48 fan belt		550,0
	Manager Company Compan	25.00	25.0
	Service labor-10/8/13;Replace pneumatic thermostat in front office of suite 101. Was asked to check another VAV and check flex ductwork for lack of support.	72.00	72.0
	Pneumatic reverse acting/2-pipe thermostat	160.00	160.0
1	Service labor-10/11/13; Replace main area pneumatic thermostat in suite 101. Was also asked to check a VAV in suite 203.	72.00	72.0
1	Pneumatic reverse acting/2-pipe thermostat	160.00	160.0
	Sales Tax	6.00%	19.2

\$1,130.20

Phone #

561-712-1126

Fax # 561-712-1407

accounting@bts-ac.com