Building Technology Services,

Phone #

561-712-1126

Fax #

561-712-1407

13833 Wellington Trace E4-157 Wellington, Florida 33414

Invoice

Project

Date	Invoice #
7/18/2011	9157

	The state of the s
Bill To	
ANR Realty Management	
PO Box 357	
Cedar Grove, N.J. 07044	

Ship To	
The Sienna at Broken Sound	
1095 Broken Sound Parkway	
Boca Raton, FL.	
1st Fl. Construction	·
•	

Terms

Quantity Description 1 City of Boca Raton-Paid change of subcontractor form filing fee on behalf of CC 1 Quoted labor price to pull a/c sub-permit, visit site 2 times to check items for mechanical inspection and test and balance equipment with a helper provided by Fred. 1 Check window a/c in back room of 1st floor construction. Cleaned condenser coil packed with construction dust and found that pressures resulting from the clogged coiled created a refrigerant leak-condemned unit. 3 7-19-11 Completed control wiring and equipment start up on construction job. 2 Add'l. hours spent on first floor build-out Sales Tax		.1.
1 City of Boca Raton-Paid change of subcontractor form filing fee on behalf of GC 1 Quoted labor price to pull a/c sub-permit, visit site 2 times to check items for mechanical inspection and test and balance equipment with a helper provided by Fred. 1 Check window a/c in back room of 1st floor construction. Cleaned condenser coil packed with construction dust and found that pressures resulting from the clogged coiled created a refrigerant leak-condemned unit. 3 7-19-11 Completed control wiring and equipment start up on construction job. 2 Add'l. hours spent on first floor build-out		
of GC Quoted labor price to pull a/c sub-permit, visit site 2 times to check items for mechanical inspection and test and balance equipment with a helper provided by Fred. Check window a/c in back room of 1st floor construction. Cleaned condenser coil packed with construction dust and found that pressures resulting from the clogged coiled created a refrigerant leak-condemned unit. 7-19-11 Completed control wiring and equipment start up on construction job. Add'l. hours spent on first floor build-out	Rate	Amount
for mechanical inspection and test and balance equipment with a helper provided by Fred. 1 Check window a/c in back room of 1st floor construction. Cleaned condenser coil packed with construction dust and found that pressures resulting from the clogged coiled created a refrigerant leak-condemned unit. 3 7-19-11 Completed control wiring and equipment start up on construction job. 2 Add'l. hours spent on first floor build-out	64.00	64.00
Check window a/c in back room of 1st floor construction. Cleaned condenser coil packed with construction dust and found that pressures resulting from the clogged coiled created a refrigerant leak-condemned unit. 7-19-11 Completed control wiring and equipment start up on construction job. Add'l. hours spent on first floor build-out	500.00	500,00
 7-19-11 Completed control wiring and equipment start up on construction job. Add'l. hours spent on first floor build-out 	72.00	72.00
	72.00	216.00
	0.00	0.00
Sales Tax	72.00 6.00%	144.00 0.00
Thank you for your business.	Total	\$996.00

ccampbell_bts@bellsouth.net

P.O. No.