Building Technology Services, Inc 13833 Wellington Trace E4-157 Wellington, Florida 33414

Invoice

Date	Invoice #
11/18/2013	92378

Bill To	
ANR Realty	
PO Box 357	
Cedar Grove, N.J. 07009	

Siena at Broken Sound	
095 Broken Sound Blvd.	
Boca Raton, FL. 33487	

P.O. No.	Terms	Project
	Net 30	

Quantity	Description	Rate	Amount
1.5	Service labor-11/25/13; A/C not cooling in 1st & 2nd fl. common area (hallway). Found 2 floor a/c with fan belt falling apart & barely turning the blower wheel. Filters clogged and generally in need of maintenance. Replaced belt & filters and performed full maintenance on system. 1st floor unit was off on float switch due to clogged drain. Also replaced plugged	72.00	108.0
2 1 1 1	filters and performed full maintenance on this system. 16x20x2 pleated filters 21.5x21.5x1 pleated filter A-35 fan belt Coil cleaner Sales Tax	16.00 5.00 21.00 7.00 6.00%	32.0 5.0 21.0 7.0 3.9
		4	
		ь	

Total \$176.90

Phone #

561-712-1126

Fax #

561-712-1407

accounting@bts-ac.com